

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	weeds unmanaged		
Corrective Action:	comply with COGCC housekeeping rules	Date:	11/05/2022
Type	OTHER		
Comment:	nt: Venting/flaring issue may be present on this site. COGCC data shows that KPK produced, and used same amount of gas since 12/1/18, Sl. From 7/1/18 to 11/1/18, previous gas production was several times more than what was used from 2018 to present. Flare sundry notices were denied for this site. Well has been shut in since 1/1/22 according to COGCC data. There is no gas measurement equipment on location, and no gas meter run as this well was part of the third creek pipeline shut down		
Corrective Action:	Comply with COGCC venting/flaring rules	Date:	05/12/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	red ag fencing		
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Bradenhead		# 1		
Comment:	plumbed to surface			
Corrective Action:			Date:	
Plunger Lift		# 1		
Comment:				
Corrective Action:			Date:	
Emission Control Device		# 1		
Comment:				
Corrective Action:			Date:	
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:			Date:	
Bird Protectors		# 1		
Comment:				

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 203809 Type: WELL API Number: 001-09369 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/28/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 10/5/22 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- BoxElder 22-28 Company Name- KPK API- 05-001-09369 In Adams County Colorado. While there, I observed PR well During this inspection the following possible compliance issues were observed:</p> <p>Venting/flaring issue may be present on this site. COGCC data shows that KPK Produced, and used same amount of gas since 12/1/18, Sl. From 7/1/18 to 11/1/18, Previous gas production was several times more than what was used from 2018 to Present. Flare sundry notices were denied for this site. Well has been shut in since 1/1/22 according to COGCC data. There is no gas measurement equipment on location, and no gas meter run as this well was part of the third creek pipeline shut down. Comply with COGCC venting/flaring rules 5/12/22 Weeds Unmanaged on location Comply with COGCC housekeeping rules 11/5/22 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	10/05/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403190886	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880956
699504244	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880942