

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/07/2022

Submitted Date:

10/07/2022

Document Number:

702500563**FIELD INSPECTION FORM**
 Loc ID 326440 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Fields, Vanessa		vfields@logosresourcesllc.com	All SW field inspections
, General		regulatory@logosresourcesllc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216494	WELL	PR	07/01/2019	GW	067-08100	BONDAD 33-9 25A	PR

General Comment:

Inspector Alex Klink on site to conduct follow up inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type UNUSED EQUIPMENT

Comment: CA from previous inspection Doc# 702500101 has been satisfactorily completed.

Corrective Action: Date: Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # & Marked

#

Comment: CA from previous inspection Doc# 702500101 has been satisfactorily completed.

Corrective Action: Date: **Tanks and Berms:**

Contents # Capacity Type Tank ID SE GPS

PRODUCED WATER 1 100 BBLS PBV STEEL

Comment: Corrective Action: Date: **Paint**Condition Other (Content) Other (Capacity) Other (Type) **Berms**

Type Capacity Permeability (Wall) Permeability (Base) Maintenance

Earth Adequate Walls Sufficient Base Sufficient Adequate

Comment: CA from previous inspection Doc# 702500101 has been satisfactorily completed.

Corrective Action: Date: **Venting:**Yes/No Comment: Corrective Action: Date: **Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 216494	Type: WELL	API Number: 067-08100	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater BMP's are not maintained along access road. Erosion on access road, erosion channel upgradient of road (IMG 03). sediment on access road originating from previously stated erosion channel (IMG 04), erosion channel along road (IMG 05, IMG 06, IMG 07).</p> <p>Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C, including ditches along access roads to minimize and control erosion and sediment migration.</p> <p>Date: 11/07/2022</p>						
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403190935	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5881004
702500564	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880995