

Inspection Photos

API: 061-06179

Operator: ENERVEST OPERATING LLC

Inspection Date: 10/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022

Inspection Photos



Photo 1. Facing east along the access road. There has been gravel spread along areas of the road. Some areas may have excess gravel that may need to be spread out better.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022

Inspection Photos



Photo 2. Facing northeast along the access road. There has been gravel spread along areas of the road for stabilization where water was pooling on the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022

Inspection Photos



Photo 3. Facing north toward the location. There is a remediation project # 19874 in process. Soils have been recontoured at the location and the location has been fenced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022

Inspection Photos



Photo 4. Facing northwest at the location. There are wattles installed at the down gradient side of the location however, wattles are not properly staked down. T-post are being used to hold wattles in place which is not adequate.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022

Inspection Photos



Photo 5. Facing west toward the location. The wattles will need to be properly staked down once the location is seeded and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022

Inspection Photos



Photo 6. Facing south at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022

Inspection Photos



Photo 7. North side of the location facing southeast. There is a metal pipe riser shown at red arrow that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022

Inspection Photos



Photo 8. Facing north at the location. It appears soils have been decompacted. It does not appear that seeding has been performed yet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06179 | Date: 10/12/2022