

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2022

Submitted Date:

10/15/2022

Document Number:

700704601

FIELD INSPECTION FORM

Loc ID 441283 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

5 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10524

Name of Operator: GRMR OIL & GAS LLC

Address: P.O. BOX 6280

City: BROOMFIELD State: CO Zip: 80021

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Chaps, Alain	443-531-8262	alainchaps@gmail.com	
Leone, John	406-493-4294	john.leone@grmroilandgas.com	
Adesoye, Yosoye	404-723-6547	yosoye@grmroilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441282	WELL	PR	08/01/2022	OW	081-07818	Myers 19-11HA	PR

General Comment:

COGCC Inspection Report Summary
 On Monday 10/14/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a complaint inspection at GRMR Meyers 19-11HA, at Location # 314509 in Moffatt county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.
 Follow up on complaint document # 403164266, OGI shows that the combustor is lit and combusting.
 During this inspection the following possible compliance issues were observed:

1. Random debris.
2. 2 of the tanks are missing information
3. Random staining
4. 1 chemical tank is unused at well head
5. Cellar is full of fluid

Refer to photograph of observed compliance issue.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	2 of the tanks are missing information		
Corrective Action:	Provide proper labeling on tanks		Date: 11/25/2022
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Cellar is full of fluid		
Corrective Action:	Evacuate fluids		Date: 10/28/2022
Type	OTHER		
Comment:	Random staining		
Corrective Action:	Remove stained material		Date: 10/28/2022
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris		Date: 10/28/2022
Type	STORAGE OF SUPL		
Comment:	One chemical tank at well head is disconnected and considered stored equipment.		
Corrective Action:	Remove or put into service chemical tank.		Date: 10/28/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment: Chemical tanks in plastic containments			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment: Well head			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 441282 Type: WELL API Number: 081-07818 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Optical Gas Imaging Survey

Survey Type: Complaint

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: SW Weather: Clear Temperature: 68 (F)

Assisting Staff: _____ Camera #: 3

Visible Smoke Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
12:30	PM	1:00	PM

Equipment
Separation Equipment
Other
Wellhead(s)
Oil Tank(s)
Water Tank(s)

Comment: OGI showed ECD is burning, also inspector witnessed through sight glass ECD is lit.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704607	OGI Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5887189
700704611	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5887190