

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/11/2022

Submitted Date:

10/14/2022

Document Number:

700704605**FIELD INSPECTION FORM**
 Loc ID 445005 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 952 ECHO LANE SUITE 480City: HOUSTON State: TX Zip: 77024**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Schmidt, Jason		jason@fulcrumef.com	
Penner, Annalee		annalee@fulcrumef.com	
Ross, Rikki		rikki@d90energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445004	WELL	PR	09/01/2020	OW	057-06551	SU 0680 3-9H16	PR
445006	WELL	PR	03/13/2019	OW	057-06552	SU 0680 6-4H	PR
458559	WELL	PR	02/01/2021	OW	057-06611	SU 0680 12-9H16	PR

General Comment:

Follow up for complaint document # 403126327. Combustor is lit and operating.

Inspected Facilities									
Facility ID:	445004	Type:	WELL	API Number:	057-06551	Status:	PR	Insp. Status:	PR
Facility ID:	445006	Type:	WELL	API Number:	057-06552	Status:	PR	Insp. Status:	PR
Facility ID:	458559	Type:	WELL	API Number:	057-06611	Status:	PR	Insp. Status:	PR
Completion									
Operation:									
Date Flowback:									
Contractor:									
Comment:									
Corrective Action:									
Date:									

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Steady Speed: _____ (mph) Direction From: S/W Weather: Partly Temperature: 54 (F)Assisting Staff: _____ Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:00	AM	11:20	AM	Other

Comment: ECD's show no signs of uncombusted VOC's with OGI camera.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704609	OGI video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5887195