

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SWSE

Location ID: 334650



Photo #8065 From entrance to location.



Photo #8066 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SWSE

Location ID: 334650



Photo #8068 Chemical tank missing required information.



Photo #8069 Debris on location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SWSE

Location ID: 334650



Photo #8070 Multiple heating insulation open ended and not capped.



Photo #8071 Debris on location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SWSE

Location ID: 334650



Photo #8072 Debris on location.