

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2022

Submitted Date:

10/11/2022

Document Number:

702500579

FIELD INSPECTION FORMLoc ID 320863 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		Inspections@catamountep.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205261	WELL	PR	03/01/2020	CBM	007-06140	PARGIN MOUNTAIN UNIT 11	PR
456218	WELL	PR	12/20/2019	CBM	007-06330	EBC 9	PR
456219	WELL	PR	12/24/2019	CBM	007-06331	EBC 10	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

1

Comment: Corrective Action: Date:

Type: Other

1

Comment: Chemical container near #10 separator. Spill prevention is nearly full from stormwater and does not have adequate capacity to prevent spills from chemical container. (IMG 03).

Corrective Action: Maintain BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.

Date: 10/16/2022

Type: Ancillary equipment

5

Comment: Telemetry, 2 electric boxes with solar panel, portable toilet, produced water transfer house.

Corrective Action: Date:

Type: Prime Mover

3

Comment: Gas powered

Corrective Action: Date:

Type: Gas Meter Run

3

Comment: Gas meter calibrations are within the last year.

Corrective Action: Date:

Type: Bradenhead

3

Comment: Bradenheads are accessible.

Corrective Action: Date:

Type: Flow Line

10

Comment: 2" line from Pargin Mountain wellhead to separator, 2 4" and 2 2" lines from #9 and #10 wellheads to separators, 3 lines from separators to produced water tanks, 2 2" lines from separators to #9 and #10 gas powered prime movers.

Corrective Action: Date:

Type: Pump Jack

3

Comment: Corrective Action: Date:

Type: Bird Protectors

3

Comment: Separator vent stacks are screened properly.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	500 BBLs	STEEL AST		37.146738,-107.382172	
Comment: 2 above ground produced water tanks, each with 500 bbl capacity.						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Plastic barrier with liner material.					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 205261 Type: WELL API Number: 007-06140 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 456218 Type: WELL API Number: 007-06330 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 456219 Type: WELL API Number: 007-06331 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Ditches	Fail			
Berms	Pass					
Ditches	Pass					
Gravel	Pass					
Culverts	Pass					

Comment: Sediment on road (IMG 04). Sediment appears to originate from up gradient erosion channel. Ditch is filled with sediment and not maintained. Access roads must be operated in a manner that minimizes erosion and transport of sediment.

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C

Date: 11/11/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403194352	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883624
702500580	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883613