

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2022

Submitted Date:

10/11/2022

Document Number:

702500589**FIELD INSPECTION FORM**Loc ID 320856 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1001 17TH STREET STE 1160City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		Inspections@catamountep.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205244	WELL	PR	01/01/2020	CBM	007-06122	BULL CREEK FEDERAL A 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

# 3

Comment: 2" line from wellhead to separator, 2" line from separator to gas powered prime mover, line from separator to produced water off location.

Corrective Action: Date: 

Type: Vertical Heated Separator

# 1

Comment: Corrective Action: Date: 

Type: Pump Jack

# 1

Comment: Corrective Action: Date: 

Type: Bird Protectors

# 1

Comment: Separator vent stack is screened

Corrective Action: Date: 

Type: Deadman # &amp; Marked

# 4

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 1

Comment: Gas meter calibration is within the last year.

Corrective Action: Date: 

Type: Prime Mover

# 1

Comment: Gas powered.

Corrective Action: Date: 

Type: Bradenhead

# 1

Comment: Bradenhead is accessible.

Corrective Action: Date: 

Type: Ancillary equipment

# 1

Comment: Telemetry

Corrective Action: Date:

<b><u>Venting:</u></b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

<b>Inspected Facilities</b>				
Facility ID: 205244	Type: WELL	API Number: 007-06122	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Sediment on access road originating from up gradient erosion channel, (IMG 04, IMG 05). Ditch is filled with sediment. Access road BMP's not maintained. Erosion channel at location entrance (IMG 03). Location BMP's not maintained. Location and access roads must be operated in a manner that minimizes erosion and transport of sediment.</p>						
<p>Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C</p>						<p>Date: 11/11/2022</p>
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403194354	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883626">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883626</a>