

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/13/2022

Submitted Date:

10/13/2022

Document Number:

679605178**FIELD INSPECTION FORM**Loc ID 429799 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429801	WELL	PR	06/01/2019	OW	123-35927	BOOTH 30-23	PR
429802	WELL	PR	11/01/2019	OW	123-35928	BOOTH 3-23	PR
429875	WELL	PR	08/23/2021	OW	123-35954	BOOTH 29-23	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No BBLS on h2o tanks and faded bbls on crude oil tanks. See attached photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/13/2022
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at one wellhead. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.	Date:	11/13/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Does not appear to be annually calibrated. See attached photo.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 11/13/2022
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					

Inspected Facilities				
Facility ID: 429801	Type: WELL	API Number: 123-35927	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
Facility ID: 429802	Type: WELL	API Number: 123-35928	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
Facility ID: 429875	Type: WELL	API Number: 123-35954	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Thursday, October 13, 2022 at approximately 12:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at BOOTH 3-23 (PDC Energy), at location #: 429799 in WELD COUNTY Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. One wellhead appears to have stained soil under the master valve. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d. (Corrective Action Date: November 13, 2022) See attached photo #2. 2. Gas meter is not annually calibrated. Calibrate gas metering equipment annually to comply with rule 430.d.(1). (Corrective Action Date: November 13, 2022) See attached photo #8. 3. H2O tanks do not display BBLS and crude oil tanks have BBLS significantly faded. Install signs to comply with Rule 605.h. (Corrective Action Date: November 13, 2022) See attached photos #4-7. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	10/13/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679605179	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5889096