

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2022

Submitted Date:

10/21/2022

Document Number:

700704624**FIELD INSPECTION FORM**Loc ID 313011 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thomas, John	505-326-2659	jthomas@rlbayless.com	
, COGCC		anna.omalley@state.co.us	
Trujillo, Helen		notices@rlbayless.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223304	WELL	PR	08/01/2020	OW	081-06668	ZIMMERMAN/CHAMBERLIN 1	PR

**General Comment:**

On Tuesday 10/18/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted an inspection on site in response of Complaint from wild earth guardians at Robert Bayless Zimmerman/Chamberlin #1, at Location # 313011 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following compliance issues were observed:

1. Load lines missing caps/plugs
2. Propane tank missing information
3. Random staining
4. Random debris
5. Dead man not marked properly
6. Stored equipment not needed for operations around production equipment and could possibly hinder emergency response. Previous inspections noted and C/A date remains 6/13/2022.
7. BMP's on cut slope are failing, cut slope not stabilized.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Propane tank missing information		
Corrective Action:	Provide proper labeling	Date:	11/11/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Load lines missing caps/plugs		
Corrective Action:	Install caps/plugs	Date:	11/11/2022
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove all debris	Date:	11/11/2022
Type	OTHER		
Comment:	Random staining		
Corrective Action:	Remove all stained/impacted material	Date:	11/11/2022
Type	STORAGE OF SUPL		
Comment:	Stored equipment not needed for operations around production equipment and could possibly hinder emergency response. Previous inspections noted and C/A date remains 6/13/2022.		
Corrective Action:	Remove or provide a variance for stored equipment	Date:	06/13/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Dead man not marked properly		
Corrective Action:	Mark or remove dead man		Date: 11/11/2022
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Well head		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Ramsey, Scott

Earth						
Comment:	Not lined					
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth						
Comment:	Not lined					
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	223304	Type:	WELL	API Number:	081-06668	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					

Comment: [BMP's on cut slope are failing, cut slope not stabilized.](#)Corrective Action: [Install or repair required BMPs](#)

Date: 12/02/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704625	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5893680">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5893680</a>