

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2022

Submitted Date:

10/17/2022

Document Number:

699805069

**FIELD INSPECTION FORM**

Loc ID 334883 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211281	WELL	PR	01/30/1996	GW	045-07040	KRK 7-15 (07EB)	PR
264556	WELL	PR	01/30/2003	GW	045-08921	KRK 7-15C (07EB)	PR
264557	WELL	PR	05/01/2022	GW	045-08922	KRK 7-16B (07EB)	PR
264558	WELL	PR	02/21/2003	GW	045-08923	KRK 7-14A (07W)	PR

**General Comment:**

COGCC Inspection Report Summary  
On Friday 10/14/22 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at CAERUS PICEANCE LLC KRK-67S92W /7SWSE. Location #334883 in Garfield County Colorado. While there, I observed normal production operations. During this inspection the following compliance issues were observed:

1) Multiple places with flow line heating insulation open ended and not capped with a corrective action date of 10/24/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Refer to equipment for corrective actions		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			

Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Multiple places with flow line heating insulation open ended and not capped.		
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.	Date:	10/24/2022
Type: Bradenhead	# 4		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Centralized containment</a>					
Corrective Action:				Date:	

<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	<u>211281</u>	Type:	<u>WELL</u>	API Number:	<u>045-07040</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>264556</u>	Type:	<u>WELL</u>	API Number:	<u>045-08921</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>264557</u>	Type:	<u>WELL</u>	API Number:	<u>045-08922</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>264558</u>	Type:	<u>WELL</u>	API Number:	<u>045-08923</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
Sediment Traps						
Ditches						
		Gravel				
		Berms				
Gravel						
Compaction						
		Ditches				
		Sediment Traps				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">Refer to Equipment for corrective actions.</span>	depaoloc	10/17/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403198739	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5887560">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5887560</a>
699805070	Photos for Insp. #699805069	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5887555">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5887555</a>