

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2022

Submitted Date:

10/19/2022

Document Number:

693805210**FIELD INSPECTION FORM**Loc ID 322382 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS ST STE 6161City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Pesicka, Conor		conor.pesicka@state.co.us	
Arnim, Rees	713-469-0275	rarnim@locin.energy	Director of Engineering
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210390	WELL	SI	06/01/2020	GW	045-06146	FEDERAL 16-4	SI

**General Comment:**

COGCC staff performed a follow up field inspection on 10/18/2022. Followup to inspection doc#693805157 on 9/8/2022.  
 Corrective action from previous inspections not completed.  
 Issues were found requiring corrective action. See inspection text and photos for details.  
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location				
<b>Lease Road:</b>				
Type	Main			
comment:	Garfield Co Rd 201			
Corrective Action	L			Date:
Type	Access			
comment:	Bunniger Rd			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign not updated to reflect current operator CA not completed			
Corrective Action:	Install sign to comply with Rule 605.g.			Date: 10/12/2022
Emergency Contact Number:				
Comment:	Sign not updated to reflect current operator CA not completed			
Corrective Action:	Install sign to comply with Rule 605.g.			Date: 10/12/2022
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PIT			
Comment:	Fence/net combo			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:				
Corrective Action:				Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210390	Type:	WELL	API Number:	045-06146	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <div>Well shut in 6/1/2020. Form 4 Doc #403054040 Alternative MIT approved 8/16/2022.</div>									
Corrective Action: _____ Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment of chemicals

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: Lat: 39.456939Long: -109.000575Reference Point: SEOther: Length: 20Width: 20**Lining:**Liner Type: Liner Condition: Comment: North pitCorrective Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: Type: BlowdownLined: NOPit ID: Lat: 39.456695Long: -109.000627Reference Point: SEOther: Length: 20Width: 20**Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment:

Inspector Name: BROWNING, CHUCK

Corrective		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective		Date:

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403202800	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5890993">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5890993</a>
693805211	Inspection photos 10/18/2022	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5890972">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5890972</a>