

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2022

Submitted Date:

10/12/2022

Document Number:

694500521**FIELD INSPECTION FORM**Loc ID 426403 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 760 HORIZON DRIVE STE 401City: GRAND JUNCTION State: CO Zip: 81506**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Paterson, Chris	970-620-3456	chris.patterson@scoutep.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
102564	PIT	AC			-	RANGLEY WEBER MAIN WTR PLANT	EI
483023	SPILL OR RELEASE	AC	10/05/2022		-	MWP P-1750 Suction Line	EI

General Comment:

On 10/6/2022 COGCC staff, Kris Neidel inspected spill 483023 that was reported to COGCC by Scout (operator). on 10/4/2022. The following was observed; Temps of 65 degrees and sunny, the previous few weeks had seen many days of precipitation, at the time of inspection the surface of the ground was dry but moist, The point of release was observed and the spill path(s) walked to the terminus point at Pit Facility 102564. It was reported that all spilled fluid went to the pit and none overtopped or bypassed the pit, this statement appears consistent with Field observations as a part of this inspection. The spill path that was reported in Doc #403186450 appears to be accurate to what was witnessed during this field inspection. Some slight hydrocarbon staining was observed on, the foundations of the buildings near the spill point and adjacent Storage Tank. No hydrocarbon staining was observed off of the Main Water Plant Facility location. Some salt staining was observed in the spill path and in what appeared to be un-impacted adjacent soil. Conditions of approval and ongoing spill remediation is taking place through the Form 19 process.

Inspected Facilities								
Facility ID:	102564	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	483023	Type:	SPILL OR	API Number: -	Status:	AC	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: spill was reported by the operator. The

Corrective Action: spill clean up is being done under spill doc 403186411.

Date: 10/01/2022

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403202536	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5890720
694500522	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5890715