

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2022

Submitted Date:

10/19/2022

Document Number:

695106890

FIELD INSPECTION FORM

Loc ID 322214 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17210
Name of Operator: CINNAMON CREEK OIL & GAS INC
Address: P O BOX 544
City: WALSH State: CO Zip: 81090

Findings:

- 10 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mills, Hellen		helening1221@yahoo.com	All Inspections
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209866	WELL	PR	10/01/2020	OW	043-05071	SMITH 1	PR

General Comment:

Location			
Lease Road:			
Type			
comment:	ROW IS A 2 TRACK ROAD.		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
Good Housekeeping:			
Type	OTHER		
Comment:	PHOTO 6: AREA OF IMPACTED SOIL UNDER GEAR BOX OF PUMPJACK. PHOTO 7: AREA OF IMPACTED SOIL AROUND WELLHEAD.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.		Date: <u>11/19/2022</u>
Type	OTHER		
Comment:	FLIR CAMPERA INDICATES THE WELLHEAD IS LEAKING IN MULTIPLE POINTS UNDER THE WELLHEAD CAP.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>11/19/2022</u>
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5: UNUSED EQUIPMENT (OLD MOTOR AND PARTS).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606.		Date: <u>11/19/2022</u>
Type	TRASH		
Comment:	PHOTO 8: TRASH AND DEBRIS JUST EAST OF WELLHEAD.		
Corrective Action:	REMOVE TRASH AND DEBRIS PER RULE 606.		Date: <u>11/19/2022</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bradenhead	# 0		corrective date
Comment:	PHOTO 9: Bradenhead inaccessible or not visible (WELL DOES NOT APPEAR TO HAVE A BRADENHEAD INSTALLED).		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: <u>11/19/2022</u>
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	<50 BBLs	STEEL AST		38.312764,-105.127939
Comment:	PHOTO 10: 2" RISER ON TOP OF CRUDE OIL TANK IS OPEN ENDED AND DOES NOT HAVE A PRESSURE RELIEF VALVE.				
Corrective Action:	Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9).				Date: 11/19/2022

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 209866 Type: WELL API Number: 043-05071 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/23/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: NA

Comment:

NOTE THAT THERE IS A BRADENHEAD TEST SUBMITTED AND THERE IS NO BRADENHEAD ON WELLHEAD.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403203119	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891376
695106891	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891368
695106892	FLIR VIDEO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891369