

Inspection Photos

Location Name: LARAMIE ENERGY LLC Blackman /14-12 Pad

Location ID: 334544



Photo #8154 From entrance to location.



Photo #8155 From entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Blackman /14-12 Pad

Location ID: 334544



Photo #8156 Pressure relief valve leaking. Refer to OGI video.



Photo #8157 Leaking pressure relief valve located on Tank #113212