

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2022

Submitted Date:

10/26/2022

Document Number:

702500683**FIELD INSPECTION FORM**Loc ID 311955 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Overright, Issac		ioverright@maralexinc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Harrison, Trish	970 759 9545	trishharrison@eis-llc.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277814	WELL	PR	01/11/2006	GW	067-09050	MARY CATHERINE 33-7-3 1	PR
294237	WELL	PR	06/03/2008	CBM	067-09475	MARY CATHERINE 33-7-3 3B	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds at #1 pump jack (IMG 03). Weeds at #3B pump jack (IMG 04).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustible material, including weeds, per rule 610.k		Date: 11/03/2022
Type	OTHER		
Comment:	Impacted material at #1 wellhead (IMG 05).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.		Date: 11/09/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Pump jacks are enclosed by wire fencing.		
Corrective Action:			Date:

Equipment:

Type: Gas Meter Run	# 2		corrective date
Comment:	Gas meter calibrations are within the last year.		
Corrective Action:			Date:
Type: Flow Line	# 6		
Comment:	2 2" lines from wellheads to separators, 2 2" lines from separators to produced water, 2 1" gas supply lines from separators to gas powered prime movers		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Gas powered		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 2		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	Separator vent stacks are screened.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 277814 Type: WELL API Number: 067-09050 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 294237 Type: WELL API Number: 067-09475 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Compaction	Pass			
Compaction	Pass					
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500684	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5897985