

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2022

Submitted Date:

10/27/2022

Document Number:

702500702**FIELD INSPECTION FORM**Loc ID 325737 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215316	WELL	PR	02/01/2017	CBM	067-06921	HUNTINGTON A 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type OTHER

Comment: Equipment on this location is enclosed by stock panel.

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment: Bradenhead is accessible.

Corrective Action:

Date:

Type: Flow Line

# 3

Comment: 2" line from wellhead to separator, 2" line from separator to gas meter run, 2" line from separator to produced water off location.

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment: Gas meter calibration is within the last year.

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: Electric

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 1

Comment: Separator vent stack is screened.

Corrective Action:

Date:

Type: Ancillary equipment

# 4

Comment: Telemetry, 2 electric cabinets, electric meter

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

<b>Inspected Facilities</b>				
Facility ID: 215316	Type: WELL	API Number: 067-06921	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Culvert at entrance of location inlet is nearly full of sediment (IMG 03), and outlet is covered by sediment (IMG 04). Culvert is not maintained. Sediment migrating onto location near gas meter run (IMG 07). Ditch is full of sediment and not maintained. Berm is diminished not maintained. Erosion channel on cut slope (IMG 05) near separator. Sediment migrating onto location from erosion channel (IMG 06). Ditch is filled with sediment and not maintained.

Corrective Action: **Install or repair/modify required BMPs per Rule 1002.f.(2)C**

Date: 11/27/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500703	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5899173">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5899173</a>