

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2022

Submitted Date:

10/21/2022

Document Number:

700704617**FIELD INSPECTION FORM**Loc ID 434520 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: P.O. BOX 12359City: SPRING State: TX Zip: 77391-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wccassistant@gmail.com	All Inspections
Snowden, Russ		Russ_Snowden@swn.com	All Inspections
, SWN		swnsandwash@swn.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434521	WELL	SI	02/01/2022	OW	107-06260	Dill Gulch 1-22	SI

General Comment:**COGCC Inspection Report Summary**

On Wednesday 10/19/2022 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at SWN Production Company Dill Gulch 1-22, at Location # 434520 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed well is shut in. Also all signage is different operator (Beeman). This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Random debris
2. Stored/Unused equipment C/A date from previous inspection remains 8/4/22
3. Random staining C/A date from previous inspection remains 8/4/22
4. Weeds around production equipment C/A date from previous inspection remains 7/27/22
5. Open hole for wildlife to enter
6. Load line lacking plug/cap

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	all signage is different operator (Beeman)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	all signage is different operator (Beeman)		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	all signage is different operator (Beeman)		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Random staining C/A date from previous inspection remains 8/4/22		
Corrective Action:	Remove all stained material	Date:	08/04/2022
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove all debris	Date:	11/01/2022
Type	STORAGE OF SUPL		
Comment:	Stored/Unused equipment C/A date from previous inspection remains 8/4/22		
Corrective Action:	Remove all stored equipment	Date:	08/04/2022
Type	WEEDS		
Comment:	Weeds around production equipment C/A date from previous inspection remains 7/27/22		
Corrective Action:	Remove all weeds throughout location	Date:	07/25/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	Tank		
Comment:	Impacted soils are present within secondary containment. From previous inspection.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition. Remove and properly dispose of impacted material as E&P waste. Properly dispose of oily waste		Date: 08/04/2022

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	well head		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	HEATED STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 434521 Type: WELL API Number: 107-06260 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 2/2022

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403205236	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5893688
700704623	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5893679