

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2022

Submitted Date:

10/29/2022

Document Number:

707600430**FIELD INSPECTION FORM**Loc ID 305111 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274275	WELL	TA	11/01/2019	OW	123-22511	WARDLAW 20-28	TA

**General Comment:**

This is a WELL inspection.  
 Well(s): 1: Temporarily Abandoned | TA.  
 Battery: Abandoned. ALL equipment has been removed.  
 Abandoned Battery SE corner GPS coordinates: 40.450013 / -104.554927

Abandoned Centralized Battery formerly served 3 Location IDs  
 (305111, 323193, 332083).  
 (Well(s): 1: Temporarily Abandoned | TA ; 2: Plugged & Abandoned | PA).

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 500px;" type="text"/>
Corrective Action:	<input style="width: 500px;" type="text"/> Date: _____

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Wellhead: Surface casing head w/ pipe and ball / needle valves.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 274275 Type: WELL API Number: 123-22511 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment:

Temporarily Abandoned | TA.  
Well disconnected from flowline.  
Battery Abandoned.  
COGCC records last production: 08/2018.  
Red PTA tag posted at well.

Form 4 on file. TA date: 02/07/2019. Approved.  
Form 21-MIT on file. Date: 02/25/2019. Approved.  
Form 6A on file. Out-of-Svc Designation.  
Date: 09/30/2021. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/07/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 10/26/2022 at approximately 12:18 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: WARDLAW-66N64W/28SESE  Location ID: 305111  Well Name(s): Wardlaw 20-28.  API: 123-22511.  Location County: Weld County, Colorado  Weather: Mostly Sunny, dry.</p> <p>While there, I observed:  Well(s): 1: Temporarily Abandoned   TA.  Battery: Abandoned. ALL equipment has been removed.  Abandoned Battery SE corner GPS coordinates: 40.450013 / -104.554927</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs (305111, 323193, 332083).  (Well(s): 1: Temporarily Abandoned   TA ; 2: Plugged &amp; Abandoned   PA).</p> <p><b>WELL STATUS COMMENT:</b>  An attempt to Plug &amp; Abandon   PA this well was made on/or about 11/04/2021.  Form 42 Notice of Start of Plugging Operations on file. Date: 10/29/2021.  Wardlaw 20-28, API: 123-22511 well GPS coordinates: 40.453131 / -104.549878  During an attempt to begin cut/cap operations, bubbles were observed.  Well has since been returned to Temporarily Abandoned   TA status.  Plans will be made for additional plugging operations in the future.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/29/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600431	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5900389">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5900389</a>