

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2022

Submitted Date:

10/31/2022

Document Number:

700300487**FIELD INSPECTION FORM**Loc ID 320912 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 900

Name of Operator: ALAMOSA DRILLING INC

Address: 8150 N. CENTRAL EXPY - STE 750

City: DALLAS State: TX Zip: 75205-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296015	WELL	PR	09/01/2018	OW	007-06253	ALBERT MARTINEZ 1	PR
477321	Domestic Tap	AC	07/23/2020		-	Domestic Tap 18NENE	AC

**General Comment:**

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	AC panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	tanks are anchored with deadmen inside containment and cable				

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms appear to be engineered to standards in floodplain rules and guidance and CA from previous inspections and conditions of AOC around floodplain berms and tank anchoring have been performed			
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**

Survey Type: \_\_\_\_\_

Current Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Calm Speed: 0-3 (mph) Direction From: NE Weather: Clear Temperature: 50 (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Wellhead(s)
				Oil Tank(s)

Comment: See attachment section for link to downloadable FLIR video of wellhead and thief hatch leak, both observed with normal sensitivity. Leak at wellhead was also audible and included some associated product on wellhead.

Corrective Action: repair/stop gas leak at wellhead per rule 608.e and operate oil tanks as ventless with sealed thief hatch 608.a(9)

Date: 11/11/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300488	tanks and containment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901603">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901603</a>
700300489	metal containment structure	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901604">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901604</a>
700300490	wellhead, no visible bradenhead access	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901605">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901605</a>
700300491	thief hatch FLIR video for west A Martinez 1 tank	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901606">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901606</a>
700300492	FLIR video - wellhead leak	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901607">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901607</a>