

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2022

Submitted Date:

10/25/2022

Document Number:

702500667**FIELD INSPECTION FORM**Loc ID 325159 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fields, Vanessa		vfields@logosresourcesllc.com	<a href="#">All SW field inspections</a>
, General		regulatory@logosresourcesllc.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214159	WELL	PR	07/01/2021	GW	067-05476	IGNACIO 33-8 5	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type OTHER

Comment: Produced water tank is enclosed by wire fencing.

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment: Bradenhead is accessible.

Corrective Action:

Date:

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Deadman # &amp; Marked

# 4

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 2

Comment: Separator vent stacks are screened properly.

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment: Gas meter calibrations are within the last year.

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 2

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 2

Comment: Telemetry, cathodic protection

Corrective Action:

Date:

Type: Flow Line

# 6

Comment: 2 2" lines from wellhead to separators, 2 2" lines from separators to gas meter run, 1" gas supply line at wellhead, 4" pig station near separators.

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		Open Top		37.117539,-107.705884	

Comment: Partially buried open topped produced water tank, with steel mesh screen covering.

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	125 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214159	Type:	WELL	API Number:	067-05476	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater erosion channel has formed on the west edge of location and continues off location (IMG 03, IMG 04, IMG 05). Channel is ~1' wide by 4" deep.

Stormwater erosion channel has formed at center of location (IMG 06). Erosion channel is ~1.5' wide and has exposed several electrical lines.

Location must be operated in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Corrective Action: **Install or repair/modify required BMPs per Rule 1002.f.(2)C**

Date: 11/25/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403208069	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5896673">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5896673</a>
702500668	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5896643">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5896643</a>