

Inspection Photos
Location Name: Albert Martinez 1A
API: 007-06256



Cut-off stub and backfilled wellhead and propane tank



Tanks

Inspection Photos
Location Name: Albert Martinez 1A
API: 007-06256



Tubing and rods coated in oily waste still stored on bare ground

Inspection Photos
Location Name: Albert Martinez 1A
API: 007-06256



Oily waste on ground, no spill response approx. 18x40"



Oily waste 10-12" diameter

Inspection Photos
Location Name: Albert Martinez 1A
API: 007-06256



East access road



West access road