

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403219652

Date Received:

11/04/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203714

Inspection Date: 05/16/2022

FIR Submit Date: 05/18/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 467272

Location Name: ELU J14 Number: FED-496 PAD County: \_\_\_\_\_

Qtrqtr: NESW Sec: 14 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.700947 Longitude: -108.137218

FACILITY - API Number: 05-103-00 Facility ID: 467272

Facility Name: ELU J14 Number: FED-496 PAD

Qtrqtr: NESW Sec: 14 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.700947 Longitude: -108.137218

CORRECTIVE ACTIONS:

3 CA# 162036

Corrective Action: Comply with Rule 606; remove and properly dispose of trash and debris both on the Location, and blown off site from the Location.

Date: 05/25/2022

Response: CA COMPLETED

Date of Completion: 08/25/2022

Operator Comment: Debris and trash were removed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

4 CA# 162037

Corrective Action: Comply with Rule 1002.b and 1002.c

Date: 06/18/2022

Response: CA COMPLETED

Date of Completion: 10/10/2022

Operator  
Comment:

The location, including perimeter stormwater controls, were constructed utilizing industry standard operating procedures, best management practices and standards permitted with BLM & COGCC at the time of approval. The stormwater controls measures were engineered to contain and disperse stormwater through infiltration, not surface discharge. Topsoil is not utilized as a perimeter control. Topsoil is stockpiled around the location. Perimeter Sediment Control Logs are in place to mitigate the potential for sediment laden discharge from the location. Stormwater collection areas are constructed in subsoils, not topsoil. There is no stormwater collection areas or sediment trap on the west-end of the location. When interim reclamation operations are conducted and topsoil is spread, grade will be returned to a natural horizon change from subsoils to topsoil.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: \_\_\_\_\_

Title: EHS

Date: 11/4/2022 2:16:46 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403219753	Photo - BMPS installed
403219756	Photo - BMPs installed 2
403219757	Photo- BMPs installed3

Total Attach: 3 Files