

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/31/2022

Submitted Date:

10/31/2022

Document Number:

702500712

**FIELD INSPECTION FORM**

Loc ID 325914 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215556	WELL	PR	10/01/2021	CBM	067-07161	TYCKSEN A 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Lube oil on wellhead has impacted surface material (IMG 03).

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 11/16/2022

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type OTHER

Comment: Separator and gas meter run are enclosed by stock panel.

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Prime Mover # 1

Comment: Electric

Corrective Action:

Date:

Type: Bird Protectors # 1

Comment: Separator vent stack is screened.

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment: Gas meter calibration is within the last year.

Corrective Action:

Date:

Type: Vertical Heated Separator # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 4

Comment: Telemetry, pump control panel, electric cabinet, electric meter.

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: Bradenhead is accessible.

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	2" line from wellhead to separator, 2" line from separator to produced water off location, 2" line from separator to gas meter run.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215556 Type: WELL API Number: 067-07161 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Gravel	Pass			
Gravel	Pass					
		Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403213923	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901567">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901567</a>
702500713	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901564">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5901564</a>