

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2022

Submitted Date:

11/09/2022

Document Number:

700300496

FIELD INSPECTION FORM

Loc ID 313504 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46685
 Name of Operator: KINDER MORGAN CO2 CO LP
 Address: 1001 LOUISIANA ST SUITE 1000
 City: HOUSTON State: TX Zip: 77002

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224309	WELL	PR	03/08/2018	CO2	083-06374	MCELMO DOME UNIT 20-37-18 YC-2	PR

General Comment:

Compliance supervisor Steve Labowskie conducted routine inspection while in area responding to complaints noticed well cellar full of discolored fluid with a portion of the protective grate missing and contacted operator. Other well cellars in area did not have standing fluid. FLIR survey did not indicate any gas leaks, there were no bubbles in standing fluid, there were no fluid leaks observed in above grade flowlines or valves. Route cause should be evaluated and cellar kept from overflowing with precipitation and wildlife protection grate/screen be kept in place.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 24-hour operator contact number posted on well sign (970-882-5522). No local emergency services number posted.

Corrective Action: Install appropriate local emergency response services number to comply with rule 605 Date: 12/09/2022

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 3		
Comment:	AC panels		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	wellhead		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224309 Type: WELL API Number: 083-06374 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Gravel				
		Compaction				
Gravel	Pass					
		Culverts	Fail			erosion at inlet, culvert partially crushed

Comment: sediment migration and erosion at inlet of culvert observed in low point between CY-1 and CY-2

Corrective Action: Install/maintain/repair BMPs on access road low area between CY-1 and CY-2 to comply with 1002.f

Date: 04/01/2023

Pits: NO SURFACE INDICATION OF PIT

