

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402564502

Date Received:

12/31/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

cogcc@kpk.com

Knop, Max

mknop@kpk.com

Schlagenhauf, Mark

mark.schlagenhauf@state.co.us

Oakman, Kari

kari.oakman@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 690102117

Inspection Date: 10/15/2020

FIR Submit Date: 10/16/2020

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqtr: SESW Sec: 34 Twp: 1N Range: 67W Meridian: 6

Latitude: 40.001946 Longitude: -104.876365

FACILITY - API Number: 05-123-00 Facility ID: 465402

Facility Name: John Weigandt Consolidation Number: _____

Qtrqtr: SESW Sec: 34 Twp: 1N Range: 67W Meridian: 6

Latitude: 40.001946 Longitude: -104.876365

CORRECTIVE ACTIONS:

1 ☒ CA# 142760

Corrective Action:

Date: 11/18/2020

Update CA section of supplemental form 19 spill report to include information pertaining to compliance of COGCC series 1100 flowline regulations:

- 1) Root cause of failure (final determination); measures taken to prevent a recurrence
- 2) Description of flowline repair, replacement and abandonment work completed (at spill ID #465402; supporting compliance of rule 1102.j. Repair)
- 3) Contact COGCC Inspector with schedule of post repair pressure testing. Perform OLF flowline pressure testing to verify integrity of repairs/ reconnections completed prior to returning the John Weigandt consolidation flowline to service (rule 1102.j.4 and 1102.O). Upload pressure testing chart to COGCC Form 19 subsequent.
- 4) Complete abandonment of the historical/ out of service 1" CS flowline per COGCC rule 1105 (ends sealed per 1105.e.4).

Response: CA COMPLETED

Date of Completion: 10/19/2020

Operator
Comment:

- 1) Root cause of the flowline failure was determined to be internal corrosion. 1200 foot section of 4-inch carbon steel flowline replaced with 3-inch HDPE flowline to prevent future corrosion issues.
- 2) 1200 foot section of 4-inch carbon steel flowline replaced with 3-inch HDPE flowline. Cut ends of HDPE flowline re-connected using carbon steel to HDPE transitions.
- 3) Off location flowline pressure test completed on October 19, 2020.
- 4) Ends of out of service 1" flowline have been capped.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed: _____

Title: Gen Manr of Air Quality

Date: 12/31/2020 1:16:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402564502	FIR RESOLUTION SUBMITTED
402564517	OLF Pressure Test

Total Attach: 2 Files