

# Final Reclamation Inspection

September 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 318461

Inspection Document #: 701900637

NESW Section 20 T2N R66W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Succo Gas Unit 3  
Location ID: 318461



**Photo 1.** 2021 aerial imagery of the well pad and tank battery.



Inspection Photos  
Location Name: Succo Gas Unit 3  
Location ID: 318461



**Photo 2.** Overview photo of the well pad taken at ground level from the eastern edge facing west.



Inspection Photos  
Location Name: Succo Gas Unit 3  
Location ID: 318461



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Succo Gas Unit 3  
Location ID: 318461



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with the reference area (see photo 5).



Inspection Photos  
Location Name: Succo Gas Unit 3  
Location ID: 318461



**Photo 5.** Well pad and tank battery reference area.



Inspection Photos  
Location Name: Succo Gas Unit 3  
Location ID: 318461



**Photo 6.** Overview photo of the tank battery taken at ground level from the western edge facing east.



Inspection Photos  
Location Name: Succo Gas Unit 3  
Location ID: 318461



**Photo 7.** Cardinal photos taken from the middle of the tank battery. left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Succo Gas Unit 3  
Location ID: 318461



**Photo 8.** Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery shows bare ground and does not appear consistent with the adjacent crop reference area (see photo 5).