

# Inspection Photos

November 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 478568

Location Name: FEDERAL/RWF 43-9

Inspection Document #: 702800919

Garfield County, CO

NESE Section 9 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FEDERAL/RWF 43-9  
Location ID: 478568



**Photo 1.** Photo taken from the location entrance shows an overview of the Location. Note pad surface compaction degradation.





Inspection Photos  
Location Name: FEDERAL/RWF 43-9  
Location ID: 478568



**Photo 2.** Photo taken from the north shows an overview of the location, including interim areas.





Inspection Photos  
Location Name: FEDERAL/RWF 43-9  
Location ID: 478568



**Photo 3.** Photo shows production equipment.





Inspection Photos  
Location Name: FEDERAL/RWF 43-9  
Location ID: 478568



**Photo 4.** Photo shows production equipment.



**Photo 5.** Photo shows production equipment.



Inspection Photos  
Location Name: FEDERAL/RWF 43-9  
Location ID: 478568



**Photo 6.** Photo shows an example of a perimeter wattle which is not in proper functioning condition; wattle is in disrepair (unstaked, losing straw) and sediment is overtopping the wattle.



**Photo 7.** Photo shows an example of a wattle which is overwhelmed by sediment which is beginning to overtop the wattle.



Inspection Photos  
Location Name: FEDERAL/RWF 43-9  
Location ID: 478568



**Photo 8.** Photo shows where a diversion ditch enters a sediment trap at the west of the location. Degradation is occurring at the ditch outlet/trap inlet. Note also stormwater flows cutting beneath wattles in the diversion ditch. See Photos 10 and 11.



**Photo 9.** Photo shows a close-up of the ditch outlet/trap inlet in Photo 8. Degradation begins where a geotextile liner ends.



Inspection Photos  
Location Name: FEDERAL/RWF 43-9  
Location ID: 478568



**Photo 10.** Photo shows degradation occurring in the diversion ditch at the northwest of the location. Concentrated flows are cutting beneath wattles in the ditch.



**Photo 11.** Refer to Photo 10 comment.





Inspection Photos  
Location Name: FEDERAL/RWF 43-9  
Location ID: 478568



**Photo 12.** Photo taken to the north of the location shows a reclaimed area adjacent to the access road, as well as stormwater controls where the road intersects a natural drainage.

