

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403204390

Date Received:
10/21/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>COGCC.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204042

Inspection Date: 08/30/2022

FIR Submit Date: 09/02/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 445862

Location Name: Mesa Number: P24-697 County: _____

Qtrqtr: SESE Sec: 24 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.502986 Longitude: -108.161794

FACILITY - API Number: 05-045-00 Facility ID: 445862

Facility Name: Mesa Number: P24-697

Qtrqtr: SESE Sec: 24 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.502986 Longitude: -108.161794

CORRECTIVE ACTIONS:

1 CA# 164313

Corrective Action: Comply with Rule 1002.f; install or repair stormwater and erosion control BMPs in accordance with good engineering practices; ensure BMPs are maintained in proper functioning condition until Location receives a passing final reclamation inspection.

Date: 09/09/2022

Response: CA COMPLETED Date of Completion: 09/20/2022

Operator Comment: Repaired and seeded erosion. Also removed sediment from traps and repaired and reinstalled rock armor inlets and outlets of the traps.

COGCC Decision: **Not Approved**

COGCC
Representative:

Per phone conversations with Operator, Inlet/outlet armoring BMPs have not been constructed with geotextile lining in conjunction with rip-rap material in accordance with good engineering practices; additional work is scheduled to comply with 1002.f.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 10/21/2022 6:51:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403204390	FIR RESOLUTION SUBMITTED
403204391	Rock armor repaired and extended

Total Attach: 2 Files