

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE.

Location ID: 335237




Photo #8401 From entrance to location.



Photo #8402 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE.

Location ID: 335237



Photo #8403 Location lacks stabilization.



Photo #8404 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE.

Location ID: 335237



Photo #8405 Location lacks stabilization.



Photo #8407 Insufficient tracking BMP at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE.

Location ID: 335237



Photo #8409 Rill erosion occurring in access road.



Photo #8410 Gully erosion occurring in access road ditch.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE.

Location ID: 335237



Photo #8411 Gully erosion occurring in access road ditch



Phot #8412 Gully erosion occurring in access road ditch

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE.

Location ID: 335237



Photo #8414 Gully erosion occurring in access road ditch



Photo #8415 Insufficient velocity checks.