

Final Reclamation Inspection

October 21st, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 336387

Inspection Document #: 701900768

SESW Section 3 T2N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Asbury V 3-14
Location ID: 336387



Photo 1. 2021 aerial imagery of the well pad and tank battery. Well pad access road remains for the equestrian facility.

Inspection Photos
Location Name:Asbury V 3-14
Location ID: 336387



Photo 2. Overview photo of the well pad taken at ground level from the northern edge facing south.

Inspection Photos
Location Name:Asbury V 3-14
Location ID: 336387



Photo 3. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name:Asbury V 3-14
Location ID: 336387



Photo 4. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with reference area (see photo 6).

Inspection Photos
Location Name:Asbury V 3-14
Location ID: 336387



Photo 5. Overview photo of the tank battery taken at ground level from the western edge facing east. Note: tank battery appears consistent with reference area (see photo 6).

Inspection Photos
Location Name:Asbury V 3-14
Location ID: 336387



Photo 6. Well pad/tank battery reference area.

