

Inspection Photos
Location Name: Bernhardt 7-16
API #123-22698



Wellhead

Inspection Photos
Location Name: Bernhardt 7-16
API #123-22698



Master valve leak and stained soil



Unused equipment