

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/30/2022

Submitted Date:

11/30/2022

Document Number:

699504314

FIELD INSPECTION FORM
 Loc ID 454900 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455121	WELL	PR	01/01/2020	OW	123-46873	ENGLISH FARMS 8-18HZX	PR
455126	WELL	PR	01/02/2019	OW	123-46878	ENGLISH FARMS 8-14HZ	PR
455128	WELL	PR	02/01/2020	OW	123-46880	ENGLISH FARMS 8-19HZ	PR
455140	WELL	PR	02/01/2020	OW	123-46892	ENGLISH FARMS 8-17HZ	PR
455142	WELL	PR	01/02/2019	OW	123-46894	ENGLISH FARMS 8-16HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

1

Comment: electric / automation

Corrective Action:

Date:

Type: Pump Jack

3

Comment:

Corrective Action:

Date:

Type: Plunger Lift

2

Comment:

Corrective Action:

Date:

Type: Prime Mover

3

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead

5

Comment: plumbed to surface

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: <u>455121</u>	Type: <u>WELL</u>	API Number: <u>123-46873</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>455126</u>	Type: <u>WELL</u>	API Number: <u>123-46878</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>455128</u>	Type: <u>WELL</u>	API Number: <u>123-46880</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>455140</u>	Type: <u>WELL</u>	API Number: <u>123-46892</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>455142</u>	Type: <u>WELL</u>	API Number: <u>123-46894</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing Well

Comment: <u>PR</u>	
Corrective Action: <u></u>	Date: <u></u>

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were calm, cold, sunny, recent snow.	medinaj	11/30/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504315	inspection pitures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932347