



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 1

Comment: Electric / automation

Corrective Action:

Date: \_\_\_\_\_

Type: Plunger Lift # 2

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Bradenhead # 3

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 433782 Type: WELL API Number: 123-37773 Status: PR Insp. Status: PR

Facility ID: 433784 Type: WELL API Number: 123-37774 Status: SI Insp. Status: SI

Facility ID: 433809 Type: WELL API Number: 123-37791 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/12/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were calm, cold, sunny, recent snow.	medinaj	11/30/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504320	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932349">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932349</a>