

# Inspection Photos

API: 043-40000

Operator: JAVERNICK OIL

Inspection Date: 12/1/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-40000 | Date: 12/1/2022

## Inspection Photos



**Photo 1.** Facing northeast at the abandoned well site. There is an abandoned power pole that remains which needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/1/2022



## Inspection Photos



**Photo 2.** Facing south toward the location. There is gravelly soils that remain and the location is not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/1/2022



## Inspection Photos



**Photo 3.** There is cable and various debris that remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/1/2022



## Inspection Photos



**Photo 4.** Facing west at the location. There is gravelly soils and debris that remains and the location is not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/1/2022



## Inspection Photos



**Photo 5.** There is a bridge timber used for the pumpjack base that needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/1/2022



## Inspection Photos



**Photo 6.** There are cement blocks that remain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/1/2022