

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2022

Submitted Date:

12/06/2022

Document Number:

696204451**FIELD INSPECTION FORM**Loc ID 322339 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS ST STE 6161City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dbenedict@locin.energy	
		hsirvent@locinoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210314	WELL	PR	09/01/2022	GW	045-06070	GOVERNMENT 2	RI
322339	LOCATION	AC			-	GOVERNMENT-66S104W 34NENE	RI

General Comment:

On 12/5/2022, Reclamation Specialist Trujillo inspected Locin Oil Corporations' Government #2 Location in Garfield County, Colorado.

This inspection is a follow-up to #696204018 to document compliance with the following corrective actions:

- Signage
- Weeds
- Stormwater

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

Refer to the "Location" and "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:	<p>Inspection #696204018 observed that stormwater, erosion control and stabilization BMPs are missing or insufficient along entire access road- erosion degradation and sediment transport evident. Inspection required Operator to comply with 1002.f.</p> <p>It was observed in this inspection that stormwater and erosion control BMPs along the access road remain missing or insufficient; erosion/degradation remains apparent along access roads. Though waterbars were observed, properly engineered outlets were not observed. Original CA/Date remains applicable.</p>		
Corrective Action:	Comply with 1002.f.; Implement and maintain BMPs to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation on access road. Ensure controls are implemented in accordance with good engineering practices and maintained in proper functioning condition; regrading alone will not be sufficient to stabilize road and manage runoff.	Date:	09/13/2022

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Signage has been posted with correct Operator information. Previous CA has been addressed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weed management, and removal of weed debris appears to have been performed on the Location, and along access road. This CA appears to have been addressed.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210314 Type: WELL API Number: 045-06070 Status: PR Insp. Status: RIFacility ID: 322339 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204452	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5935543