

# Interim Reclamation and Stormwater Inspection

Date: 12/01/2022

Operator: FUNDARE RESOURCES OPERATING COMPANY - 10773

Location ID: 420243

Inspection Document #: 696105630

Weld County, CO

NWNW Section 36 T10N R59W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Terrace 36-11H  
Location ID: 420243



**Photo 1.** Taken near the location entrance, facing north. Photo illustrates presence of undesirable vegetation (e.g. kochia and russian thistle) outlined in red.



Inspection Photos  
Location Name: Terrace 36-11H  
Location ID: 420243



**Photo 2.** Facing west at pump jack. Photo illustrates the berm around the condensate tank is inadequate as the eastern berm wall is degrading/eroded away.



Inspection Photos  
Location Name: Terrace 36-11H  
Location ID: 420243



**Photo 3.** Close-up photo of pump jack motor, illustrating the oily stained/saturated foundation.

Inspection Photos  
Location Name: Terrace 36-11H  
Location ID: 420243



**Photo 4.** Taken from the north side of the pump jack, facing southwest. Photo illustrates debris (window) that needs to be removed and oily stained soil near building.



Inspection Photos  
Location Name: Terrace 36-11H  
Location ID: 420243



**Photo 5.** Taken from the southern end of pump jack, facing northwest. Photo illustrates oily stained soil near exhaust.



Inspection Photos  
Location Name: Terrace 36-11H  
Location ID: 420243



**Photo 6.** Taken from the western portion of the location, facing south. Photo illustrates evidence of undesirable vegetation (e.g. russian thistle and kochia) and also shows areas of bare soil within the cut slope for the location.