

Inspection Photos
Location: Hladky O'Gorman
Facility ID: 480225



Photo 1 –



Photo 2 –

Inspection Photos
Location
Facility ID:



Photo 3 – Weeds overgrown



Photo 4 –

Inspection Photos
Location
Facility ID:



Photo 5 – Frozen groundwater



Photo 6 –

Inspection Photos
Location
Facility ID:



Photo 7 –



Photo 8 –

Inspection Photos
Location
Facility ID:



Photo 9 –



Photo 10 –

Inspection Photos
Location
Facility ID:



Photo 11 –



Photo 12 –

Inspection Photos
Location
Facility ID:



Photo 13 –



Photo 14 –

Inspection Photos
Location
Facility ID:



Photo 15 –



Photo 16 –

Inspection Photos
Location
Facility ID:




Photo 17 – Inadequate fencing around the excavation




Photo 18 –

Inspection Photos
Location
Facility ID:



Photo 19 –




Photo 20 –

Inspection Photos
Location
Facility ID:



Photo 21 –



Photo 22 –

Inspection Photos
Location
Facility ID:



**Photo 23 – Weeds overgrown around separator.
Separator is not visible due to amount of weeds**




Photo 24 –

Inspection Photos

Location

Facility ID:



Photo 25 –