

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2022

Submitted Date:

12/10/2022

Document Number:

706700074**FIELD INSPECTION FORM**Loc ID 434842 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 952 ECHO LANE SUITE 480City: HOUSTON State: TX Zip: 77024**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Spear, Sam		sspear@polaris.energy	
Jacobson, Eric		eric.jacobson@state.co.us	COGCC ENG
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434841	WELL	SI	03/01/2022	OW	073-06559	BIG SKY 14-11	SI

General Comment:

Routine Field Inspection

402744622 NOAV -00 319.b - Temporary Abandonment: Resolved - N

309 - Operator's Monthly Report of Operations: Resolved - N

326.c - MIT - Temporarily Abandoned Wells: Resolved - N

IN PROCESS 7/12/2021 7/12/2021 D90 ENERGY LLC

MIT Inspection: 688310395 INSP (CA 0) APPROVED 4/27/2021 4/27/2021 D90 ENERGY LLC

Last Form 17:

402907597 17 -00 Test Date: 12/22/2021

Init Surf Casing Pressure: 0

End Surf Casing Pressure: 0

Samples Taken: N; Gas - N, Liquid - N APPROVED 12/22/2021 12/22/2021 D90 ENERGY LLC

403092212 09 (I) Change of Operatorship - Intent

Selling: D90 ENERGY LLC; Buying: POLARIS PRODUCTION OPCO LLC IN PROCESS 11/18/2022 8/25/2022 D90 ENERGY LLC

403118744 09 (S) Change of Operatorship - Subsequent

Selling: D90 ENERGY LLC; Buying: POLARIS PRODUCTION OPCO LLC IN PROCESS 8/4/2022 7/29/2022 POLARIS PRODUCTION OPCO LLC

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	lease sign at CR 35		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-683-6096

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 434841 Type: WELL API Number: 073-06559 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: This well is TA, not SI. See attached photos.

MIT inspection:

688310395 INSP (CA 0) APPROVED 4/27/2021 4/27/2021 D90 ENERGY LLC

Corrective Action: Submit Form 4 as directed by Rule 434.b. Contact COGCC ENG on this inspection.

Date: 01/13/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: [dryland crop field](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403256477	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5940433
706700114	D90 Energy Big Sky 14-11	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5940428