

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2022

Submitted Date:

12/13/2022

Document Number:

697601972**FIELD INSPECTION FORM**Loc ID 317861 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Meis, Craig		cmeis@kpk.com	<a href="#">KPK Environmental</a>
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Graber, Nikki		nikki.graber@state.co.us	
-, Marcom		primarycontractor@marcomllc.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240082	WELL	PR	08/01/2020	OW	123-07870	CARL R DEEPE B 1	EI
481108	OFF-LOCATION FLOWLINE	AC	11/29/2021		-	Wellhead Line 22NENW	EI

**General Comment:**

This is an environmental inspection of Remediation Spill ID 317861 Carl R Deepe B1. Any corrective actions from previous inspections or forms that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos are attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Wellhead signage has been updated and is legible.

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds are overgrown around the pumpjack		
Corrective Action:	Comply with Rule 606	Date:	12/20/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:	Stained soil was found at the piping adjacent to the wellhead. The stained soil has a very strong odor.		
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.		Date: 12/20/2022

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240082	Type: WELL	API Number: 123-07870	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

Facility ID: 481108	Type: OFF-	API Number: -	Status: AC	Insp. Status: EI
---------------------	------------	---------------	------------	------------------

**COGCC Comments**

Comment	User	Date
Battery and vault no longer on site. Reclamation is observed to have begun at the site of the vault/battery.	ahmadiiaa	12/13/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403260084	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5943574">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5943574</a>
697601974	Photo Documentation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5943566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5943566</a>