

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/19/2022

Submitted Date:

12/20/2022

Document Number:

707800037

**FIELD INSPECTION FORM**
 Loc ID 335068 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210475	WELL	PR	04/12/1995	GW	045-06231	CLOUGH 20	PR
284621	WELL	PR	05/08/2006	GW	045-12244	CLOUGH RWF 323-15	PR
284622	WELL	PR	05/08/2006	GW	045-12243	CLOUGH RWF 413-15	PR
284623	WELL	PR	10/20/2008	GW	045-12242	CLOUGH RWF 524-15	PR
284624	WELL	PR	10/19/2008	GW	045-12241	CLOUGH RWF 514-15	PR
284625	WELL	PR	05/08/2006	GW	045-12240	CLOUGH RWF 523-15	PR
284626	WELL	PR	09/21/2006	GW	045-12239	CLOUGH RWF 424-15	PR
284627	WELL	PR	04/02/2007	GW	045-12238	CLOUGH RWF 23-15	PR
284628	WELL	PR	04/02/2007	GW	045-12237	CLOUGH RWF 423-15	PR
284629	WELL	PR	05/08/2006	GW	045-12236	CLOUGH RWF 414-15	PR
284630	WELL	PR	10/20/2008	GW	045-12235	CLOUGH RMV 157-15	PR
284641	WELL	PR	09/30/2008	GW	045-12246	CLOUGH RWF 324-15	PR
284642	WELL	PR	04/02/2007	GW	045-12245	CLOUGH RWF 314-15	PR
294713	WELL	PR	09/30/2008	GW	045-15577	CLOUGH RWF 534-15	PR

**General Comment:**

COGCC Inspection Report Summary

On Monday 12/19/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Clough 20, at Location # 335068 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. Location is snow covered. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization/ compaction.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	210475	Type:	WELL	API Number:	045-06231	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284621	Type:	WELL	API Number:	045-12244	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284622	Type:	WELL	API Number:	045-12243	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284623	Type:	WELL	API Number:	045-12242	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284624	Type:	WELL	API Number:	045-12241	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284625	Type:	WELL	API Number:	045-12240	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284626	Type:	WELL	API Number:	045-12239	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284627	Type:	WELL	API Number:	045-12238	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	284628	Type:	WELL	API Number:	045-12237	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

Facility ID:	284629	Type:	WELL	API Number:	045-12236	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

Facility ID:	284630	Type:	WELL	API Number:	045-12235	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

Facility ID:	284641	Type:	WELL	API Number:	045-12246	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

Facility ID:	284642	Type:	WELL	API Number:	045-12245	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

Facility ID:	294713	Type:	WELL	API Number:	045-15577	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1. Location shows signs of lack of stabilization/ compaction.Corrective Action: Install or repair required BMPs in order to achieve stabilization on locationDate: 01/31/2023**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800047	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5952953">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5952953</a>