

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2022

Submitted Date:

12/22/2022

Document Number:

707800063

FIELD INSPECTION FORM

 Loc ID 335569 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271782	WELL	PR	08/23/2004	GW	045-09957	FEDERAL RWF 12-18	PR
271783	WELL	PR	09/01/2020	GW	045-09956	FEDERAL RWF 21-18	PR
271812	WELL	PR	08/22/2004	GW	045-09960	FEDERAL RWF 11-18	PR
277165	WELL	PR	01/13/2015	GW	045-10619	FEDERAL RWF 312-18	PR
277166	WELL	PR	11/01/2008	GW	045-10618	FEDERAL RWF 311-18	PR
277167	WELL	PR	03/03/2006	GW	045-10617	FEDERAL RWF 321-18	PR
296043	WELL	PR	09/01/2022	GW	045-15906	FEDERAL RWF 534-7	PR
296044	WELL	PR	05/15/2008	GW	045-15905	FEDERAL RWF 433-7	PR
296045	WELL	PR	09/01/2022	GW	045-15904	FEDERAL RWF 34-7	PR
296046	WELL	PR	03/31/2009	GW	045-15903	FEDERAL RWF 411-18	PR
296047	WELL	PR	03/31/2009	GW	045-15902	FEDERAL RWF 521-18	PR
296048	WELL	PR	02/01/2021	GW	045-15901	FEDERAL RWF 421-18	PR
296049	WELL	PR	05/15/2008	GW	045-15900	FEDERAL RWF 333-7	PR
296050	WELL	PR	05/15/2008	GW	045-15899	FEDERAL RWF 334-7	PR
296051	WELL	PR	03/31/2009	GW	045-15898	FEDERAL RWF 434-7	PR

General Comment:

COGCC Inspection Report Summary

On Wednesday 12/21/2022, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 21-18, at Location # 335569 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following compliance issues were observed:

1. Staining with strong hydrocarbon odor

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	Snow covered		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	OTHER		
Comment:	Staining with strong hydrocarbon odor		
Corrective Action:	Remove all stained material		Date: 01/05/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 15		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 15		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	271782	Type:	WELL	API Number:	045-09957	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	271783	Type:	WELL	API Number:	045-09956	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	271812	Type:	WELL	API Number:	045-09960	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	277165	Type:	WELL	API Number:	045-10619	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	277166	Type:	WELL	API Number:	045-10618	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	277167	Type:	WELL	API Number:	045-10617	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	296043	Type:	WELL	API Number:	045-15906	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	296044	Type:	WELL	API Number:	045-15905	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID: 296045	Type: WELL	API Number: 045-15904	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 296046	Type: WELL	API Number: 045-15903	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 296047	Type: WELL	API Number: 045-15902	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 296048	Type: WELL	API Number: 045-15901	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 296049	Type: WELL	API Number: 045-15900	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 296050	Type: WELL	API Number: 045-15899	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 296051	Type: WELL	API Number: 045-15898	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800071	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5957925