

Inspection Photos

API: 061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 12/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 12/20/2022

Inspection Photos



Photo 1. Facing north along the access road which has not been recontoured and reclaimed. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 12/20/2022

Inspection Photos



Photo 2. Facing northwest toward the former tank battery site located 300' southwest of the well site. The access road has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 12/20/2022

Inspection Photos



Photo 3. Facing southwest toward the former tank battery site located 300' southwest of the well site. This area has been recontoured and pipe risers have been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 12/20/2022

Inspection Photos



Photo 4. Facing south at the recontoured battery site. There are no stormwater controls installed down gradient and bare soils are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 12/20/2022

Inspection Photos



Photo 5. Facing north toward the well site. The access road has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 12/20/2022

Inspection Photos



Photo 6. Facing northeast toward the abandoned well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to erosion. This area has been recontoured and decompacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 12/20/2022