

Final Reclamation Inspection

September 18th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 309667

Inspection Document #: 701900727

NWSW Section 33 T5N R63W

Corey McDonough
Reclamation Contractor, COGCC



CO L O R A D O

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hergenreder 13-33U
Location ID: 309667



Photo 1. 2020 aerial imagery of the well pad and tank battery. Note: could not identify access road from historical imagery.

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 2. Overview photo of the well pad taken at ground level from the northern edge facing south.



Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: well pad appears consistent with adjacent crop reference area (see photo 5).

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 5. Well pad reference area.

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 6. Overview photo of the tank battery. Note: gravel remains throughout the disturbance and is being used for hay storage.

