

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2022

Submitted Date:

12/23/2022

Document Number:

707800076**FIELD INSPECTION FORM**Loc ID 335810 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272507	WELL	PR	09/01/2021	GW	045-10089	FEDERAL RWF 22-18	PR
272529	WELL	PR	02/01/2012	GW	045-10093	FEDERAL RWF 322-18	PR
272530	WELL	PR	02/09/2005	GW	045-10092	FEDERAL RWF 332-18	PR
272531	WELL	PR	09/01/2021	GW	045-10091	FEDERAL RWF 32-18	PR
277377	WELL	PR	04/01/2012	GW	045-10691	FEDERAL RWF 531-18	PR
277378	WELL	PR	02/08/2006	GW	045-10692	FEDERAL RWF 431-18	PR
277379	WELL	PR	12/08/2005	GW	045-10693	FEDERAL RWF 331-18	PR
277380	WELL	PR	05/01/2007	GW	045-10694	FEDERAL RWF 31-18	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 12/21/2022, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 322-18, at Location # 335810 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following compliance issues were observed:

1. Random debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Snow covered		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	12/30/2022

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 8		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities						
Facility ID:	272507	Type:	WELL	API Number: 045-10089	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:					Date:	
Facility ID:	272529	Type:	WELL	API Number: 045-10093	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:					Date:	
Facility ID:	272530	Type:	WELL	API Number: 045-10092	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:					Date:	
Facility ID:	272531	Type:	WELL	API Number: 045-10091	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:					Date:	
Facility ID:	277377	Type:	WELL	API Number: 045-10691	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:					Date:	
Facility ID:	277378	Type:	WELL	API Number: 045-10692	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:					Date:	
Facility ID:	277379	Type:	WELL	API Number: 045-10693	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:					Date:	
Facility ID:	277380	Type:	WELL	API Number: 045-10694	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:					Date:	

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403270837	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5957928">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5957928</a>
707800077	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5957927">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5957927</a>