

Inspection Photos

12/27/2022

Operator: LARAMIE ENERGY LLC #10433

Location #452807

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the location from west, northwest, northeast to east.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



Photo 2: See comment under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



December 27, 2022

Photo 3: Photo shows pump equipment on the southwest end of the location. Fluids were observed spilling/releasing from equipment (yellow arrow). Operator appears to have placed a shallow container beneath leak point of pump in attempt to contain fluids- fluids observed spilling over container (red arrow). Secondary containment at pump is also not in proper functioning condition/inadequate to contain a spill or release



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



Photo 4: Photo shows connection points at pipes adjacent to the produced water tanks on the southwest end of the Location. Fluids were observed releasing onto the pad surface.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



Photo 5: Photo taken from pump on the northwest end of the Location. Snow and Ice observed below the connection point of the pump appears to be impacted, and contained a red discoloration. Impacts require removal/clean-up. Secondary containment at pump is not in proper functioning condition/inadequate to contain a spill or release

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



Photo 6: Photo taken from the pump observed on the east end of the Location. Photo shows secondary containment at pump is not in proper functioning condition/inadequate to contain a spill or release



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



Photo 7: Photos provide examples of containers/buckets/totes observed on the Location missing BMPs to prevent or contain a spill. Photo right also example of totes observed on Location missing content identification labelling information.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



Photo 8: Photo shows wildlife protection devices missing from containment BMP.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #452807



Photo 9: Photo shows what appears to be various tarp or liner material within a snow/dirt pile. Material is considered debris and required removal and proper disposal.

