

Inspection Photos

API: 055-06295

Operator: PETROGLYPH OPERATING CO

Inspection Date: 1/6/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06295 | Date: 1/6/2023

Inspection Photos



Photo 1. Facing east along the two track access road which was not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 1/6/2023

Inspection Photos



Photo 2. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 1/6/2023

Inspection Photos



Photo 3. Facing South toward the cut slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 1/6/2023

Inspection Photos



Photo 4. There is an erosion channel along the cut slope which was not repaired since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 1/6/2023

Inspection Photos



Photo 5. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 1/6/2023