

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2023

Submitted Date:

01/05/2023

Document Number:

699504363

FIELD INSPECTION FORMLoc ID 320538 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 79905

Name of Operator: SMITH OIL PROPERTIES INC

Address: PO BOX 219

City: BYERS State: CO Zip: 80103

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shelley, Vicki	303-825-7405	smithoilprop@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279864	WELL	SI	06/01/2018	GW	001-09552	VICKI 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	weeds unmanaged on location		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	02/05/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused pump jack is being stored on location, needs to be removed.		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	02/05/2023
Type	OTHER		
Comment:	Well has been shut in for longer than 2 years, and is in need of MIT Contact COGCC engineering.		
Corrective Action:	Comply with COGCC mechanical integrity testing rules for shut in wells.	Date:	01/05/2023

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS			
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:	shares containment with oil tanks					Date:
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST			
Comment:						Date:
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						Date:
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						Date:
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						Date:
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 279864 Type: WELL API Number: 001-09552 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 03/04/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/4/23 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Vicki 1</p> <p>Company Name- Smith Oil Porperties INC</p> <p>API- 05-001-09552</p> <p>In Weld/Adams/Denver County Colorado.</p> <p>While there, I observed SI well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>weeds unmanaged on location</p> <p>Comply with COGCC housekeeping rules 2/5/2023</p> <p>Well has been shut in for longer than 2 years, and is in need of MIT Contact COGCC engineering.</p> <p>Comply with COGCC mechanical integrity testing rules for shut in wells. 1/5/23</p> <p>Unused pump jack is being stored on location, needs to be removed.</p> <p>Comply with COGCC housekeeping rules 2/5/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	01/05/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504364	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5978055