

# Inspection Photos

API: 009-06449

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06449 | Date: 1/10/2023

## Inspection Photos



**Photo 1.** Facing west at the beginning of the access road. The cattle guard has not been removed and the road is not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06449 | Date: 1/10/2023

## Inspection Photos



**Photo 2.** Facing south toward the location which has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06449 | Date: 1/10/2023

## Inspection Photos



**Photo 3.** Facing southwest toward the location. There is compacted soil where the road remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06449 | Date: 1/10/2023

## Inspection Photos



**Photo 4.** Facing east at the location.



## Inspection Photos



**Photo 5.** Facing north at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06449 | Date: 1/10/2023

## Inspection Photos



**Photo 6.** Facing northwest toward the surrounding undisturbed reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06449 | Date: 1/10/2023