

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8747 From entrance to location.



Photo #8748 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Network: Jan 11, 2023 at 11:55:17 AM MS
Local: Jan 11, 2023 at 11:55:17 AM MS

Photo #8749 From entrance to location.



Network: Jan 11, 2023 at 11:55:20 AM MS
Local: Jan 11, 2023 at 11:55:20 AM MS

Photo #8750 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8751 From entrance to location.



Photo #8752 Undesirable plant species on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8753 Undesirable plant species on location.



Photo #8039 From inspection #699805051 conducted on 10/12/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8040 From inspection #699805051 conducted on 10/12/22.



Photo #8771 Undesirable plant species on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8756 Undesirable plant species on location.



Photo #8757 Undesirable plant species on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8763 Stained soils and gravel on location.



Photo #8766 Stained soils and gravel on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8767 Stained soils and gravel on location.



Photo #8768 Stained soils and gravel on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8764 Multiple places with unused equipment.



Photo #8779 Multiple places with unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8775 Drain valves open with stained gravel under valve and hose.



Photo #8776 Hole in secondary containment and stained gravel.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8777 Multiple holes in tank containment.




Photo #8778 Multiple holes in tank containment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER-66S92W /18SWSE

Location ID: 311676



Photo #8757 Dever A12 Wellhead leaking.



Photo #8758 Dever A12 Wellhead leaking.